



Dear Customer,

Misted Screen, please be aware that the Freeway II has been extensively tested in wet conditions, it was found during testing that under some conditions once the trolley was stored away after wet testing the screen could mist up, we also found that the moisture tended to dry up quite quickly and had no detrimental effect on either the trolley or its electronics. Residual water will stay on the trolley when it has been used in wet conditions, once the trolley is then stored in a warmer environment then of course this creates moisture which appears on the inside of the screen as mist.

A trolley kept in warm damp conditions (utility room for example) then taken out into cold conditions may also mist up initially, this will dissipate and there will be no damage to the trolley.

Mist on the inside of the screen will normally dry up quite quickly if the trolley is in warm dry conditions.